

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 150 From entrance to location



Photo # 151 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 152 Location



Photo # 153 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 154 Location



Photo # 155 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 156 Location



Photo # 157 Dead weeds/debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 158 Dead weeds/debris



Photo # 159 Dead weeds/debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BUXTON RWF 23-30 pad

Location ID: 335503



Photo # 160 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 161 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules