

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 476 From entrance to location



Photo # 477 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 478 Location



Photo # 479 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 480 Location



Photo # 481 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7496 From inspection 708903824 conducted on 05/16/2024 Open ended load line

Photo # 482 Open ended load line

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 483 Sign has mud on it & some required info is obscured