

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 636 From entrance to location



Photo # 637 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 638 Location



Photo # 639 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 640 Wellhead sign is weathered & peeling/some required info is starting to become illegible




Photo # 641 Wellhead sign is weathered & peeling/some required info is starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487




Photo # 642 Wellhead sign is weathered & peeling/some required info is starting to become illegible



Photo # 643 Wellhead sign is weathered & peeling/some required info is starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 644 Possible integrity issue with RWF 23-31 well casing valve



Photo # 645 Possible integrity issue with RWF 23-31 well casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 646 Possible integrity issue with RWF 23-31 well casing valve



Photo # 647 Possible integrity issue with RWF 23-31 well casing valve