

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Guy line anchor is not marked		
Corrective Action:	Comply with rule 1003 a.	Date:	06/06/2024
Type	OTHER		
Comment:	no gas measurement equipment on location		
Corrective Action:	Comply with rule 430	Date:	06/06/2024
Type	OTHER		
Comment:	OOSLOT risers are not LOTO		
Corrective Action:	Comply with rule 1105	Date:	06/06/2024
Type	OTHER		
Comment:	contaminated soil by wellhead		
Corrective Action:	Comply with rule 905 e.	Date:	06/06/2024
Type	OTHER		
Comment:	Unable to access location due to locks on ranch gates		
Corrective Action:	Comply with rule 204	Date:	06/06/2024
Type	WEEDS		
Comment:	Weeds unmanaged on location		
Corrective Action:	Comply with rule 606	Date:	06/06/2024
Type			
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Oil production has has been updated since 12/1/23		
Corrective Action:	Comply with rule 429.	Date:	06/06/2024
Type	OTHER		
Comment:	Wellhead sign is inadequate		
Corrective Action:	Comply with rule 605 d.	Date:	06/06/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	6' hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201199 Type: WELL API Number: 001-06602 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 6/5/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Linnebur 1 Company Name- Fritzier Resources API- 05-001-06602 In Adams County Colorado. While there, I observed PR well, no production data since 12/1/2023 During this inspection the following possible compliance issues were observed: Weeds. Rule 606. 6/6/24 Contaminated soil. Rule 905 e. 6/6/24 Access. Rule 204. 6/6/24 Wellhead sign. Rule 605d. 6/6/24 OOSLOT risers. Rule 1105. 6/6/24 Guy Line Anchor Marker. Rule 1003 a. 6/6/24 Oil production reporting. Rule 429. 6/6/24 No gas measurement equipment. Rule 430. 6/6/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	06/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403816646	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577173
699505914	inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6577142