

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2024

Submitted Date:

06/07/2024

Document Number:

701104010

FIELD INSPECTION FORM

Loc ID 314214 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273473	WELL	PR	10/18/2004	GW	099-06879	STATE 1-14	EG

General Comment:

Flowline integrity inspection

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	No well head sign Comply with Rule 605.d.(1)		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	no labels on barrels.		
Corrective Action:	Comply with Rule 605.h.(3)	Date:	06/22/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused tubing on location. Junk around compressor. Unused flowlines in fenced area. Open ended unused lines with OOSLAT.		
Corrective Action:	OOSLAT unused lines immediately until lines are removed. Remove unused flowlines. Remove unused junk from location. Comply with Rule 606	Date:	07/31/2024

Overall Good:

Spills:

Type	Area	Volume	
Comment:	Tipped over barrel with spilled fluids at the compressor. Operator was notified by email May 31, 2024 with photos included.		
Corrective Action:	Report and clean up spill Comply with Rule 912	Date:	06/10/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 273473 Type: WELL API Number: 099-06879 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Barrels without secondary containment

Comment: Barrels without secondary containment

Corrective Action: Store barrels in secondary containment.

Date: 06/22/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403817458	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578139
701104011	Flowline integrity inspection 701104010 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578136