

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2024

Submitted Date:

06/07/2024

Document Number:

710500310

FIELD INSPECTION FORM

Loc ID: 426430 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426435	WELL	PR	05/01/2012	CBM	071-09898	Champion 44-9 R	EI

General Comment:

This is an Environmental Inspection for the Champion 44-9 R well location located in Las Animas County, Co

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	WDID Sticker not present Update sign to comply with Rule 605.g.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: Packing leak observed at the time of inspection. Contacted Ed Romero, Production Foreman on 6/5/2024 @ 11.33 a.m. Lease operator dispatched to repair. ENR contacted ECMC @ 2:09 p.m. indicating packing leak repaired.

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PLASTIC AST		,
Comment:	Produced water tank near separator is broken and is missing cap				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: <u>07/09/2024</u>

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 426435 Type: WELL API Number: 071-09898 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403817828	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578596
710500311	Inspection 710500310, location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578587