

Inspection Photos

API: 009-06539

Operator: SANDLIN OIL CORP

Inspection Date: 6/13/2024

County: BACA



Inspection Photos



Photo 1. Facing southeast at the location. There are areas where the crop has not re-established.



Inspection Photos



Photo 2. Facing south at the location. There are areas where the crop has not re-established.



Inspection Photos



Photo 3. Facing east at the location. There are areas where the crop has not re-established.



Inspection Photos



Photo 4. Facing south toward the surrounding crop which has a uniform crop cover..

