

Inspection Photos

API: 009-06309

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 6/13/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. There is rutted areas along the road that need maintenance.



Inspection Photos

June 13, 2024



Photo 2. Facing southwest at the location.



Inspection Photos



Photo 3. Facing northwest toward the wellsite.



Inspection Photos



Photo 4. The berm around the tank is worn down and needs to be rebuilt.



Inspection Photos



Photo 5. Facing southwest. There is no berm around the north and west side of the tank battery to prevent a spill. The labels on the tanks are faded and worn off.



Inspection Photos



Photo 6. Facing south at the location. There is no secondary containment at the tank shown in the photo.



Inspection Photos



Photo 7. Facing toward the engine compressor. There is oil stained soils from the compresoor leaking lube oil.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06309 | Date: 6/13/2024

Inspection Photos



Photo 8. There is oily fluids in the engine skid that must be cleaned up.



Inspection Photos



Photo 9. There are two unused meter sheds that need to be removed per Rule 606.



Inspection Photos



Photo 10. Facing east at the location. There are tow pieces of equipment not in use “out of service” that nedd to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06309 | Date: 6/13/2024