

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2024

Submitted Date:

06/14/2024

Document Number:

696306415

FIELD INSPECTION FORM

Loc ID 435952	Inspector Name: PETRIE, ERICA	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 8960 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY Address: 555 17TH STREET SUITE 3700 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435953	WELL	PR	09/01/2023	OW	123-38878	State Antelope D14-X44-2HNC	PR
435954	WELL	PR	09/01/2023	OW	123-38879	State Antelope 14-44-2HNC	PR
435955	WELL	PR	09/01/2023	OW	123-38880	State Antelope D-X-2HNC	PR
449330	WELL	PR	01/16/2019	OW	123-44262	State Antelope J24-2-14XRLNB	PR
449331	WELL	PR	02/06/2019	OW	123-44263	State Antelope 14-2-14XRLNB	PR
449332	WELL	PR	01/11/2019	OW	123-44264	State Antelope E-2-14XRLNB	PR
449333	WELL	PR	01/16/2019	OW	123-44265	State Antelope J14-2-14XRLNB	PR
454853	WELL	PR	03/01/2024	OW	123-46747	State Antelope 24-2-14XRLNB	PR

General Comment: This is a Follow-Up Inspection to FIR 696305468
--

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	South East Oil Tanks missing NFPA Labels. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/12/2024

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Riser has been marked		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	435953	Type:	WELL	API Number: 123-38878	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	435954	Type:	WELL	API Number: 123-38879	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	435955	Type:	WELL	API Number: 123-38880	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	449330	Type:	WELL	API Number: 123-44262	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	449331	Type:	WELL	API Number: 123-44263	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	449332	Type:	WELL	API Number: 123-44264	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	449333	Type:	WELL	API Number: 123-44265	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	454853	Type:	WELL	API Number: 123-46747	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection. South East Oil Tanks missing NFPA Labels	petrie	06/14/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306416	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587766