

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2024

Submitted Date:

06/17/2024

Document Number:

708302314

FIELD INSPECTION FORM

Loc ID 334627	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
------------------	------------------------------------	---	-------------------	--

Operator Information: ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635	ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
--	---

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210921	WELL	PR	02/13/2014	GW	045-06679	GV 81-5	PR
274730	WELL	PR	02/19/2005	GW	045-13382	PA 411-5	PR
274939	WELL	PR	02/25/2005	GW	045-13443	PA 511-5	PR
287291	WELL	PR	10/05/2006	GW	045-12951	PA 312-5	PR
287292	WELL	PR	10/05/2006	GW	045-12950	PA 12-5	PR
287293	WELL	PR	10/05/2006	GW	045-12949	PA 412-5	PR
287294	WELL	PR	10/05/2006	GW	045-12948	PA 512-5	PR
287804	WELL	PR	07/23/2007	GW	045-13041	PA 522-5	PR

General Comment: COGCC Inspection Report Summary On 6/14/2024 at approximately 10:15, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW at Location ID #334627 in Garfield County, Colorado. Normal production operations were observed. During the inspection, the following compliance issues were observed: 1) Open wellhead cellars A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.
--

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open wellhead cellars.		
Corrective Action:	Protect wellhead cellars to comply with Rule 602.c.	Date:	08/18/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 14			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 8			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 8			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 8			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 14			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Inspected Facilities						
Facility ID:	210921	Type:	WELL	API Number: 045-06679	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	274730	Type:	WELL	API Number: 045-13382	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	274939	Type:	WELL	API Number: 045-13443	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	287291	Type:	WELL	API Number: 045-12951	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	287292	Type:	WELL	API Number: 045-12950	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	287293	Type:	WELL	API Number: 045-12949	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	287294	Type:	WELL	API Number: 045-12948	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	287804	Type:	WELL	API Number: 045-13041	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Rip Rap				
		Sediment Traps				
		Ditches				
		Gravel				
		Compaction				
Compaction						
		Tracking Pad				
Berms						
Gravel						
		Check Dams				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302315	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590389