

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2024

Submitted Date:

06/11/2024

Document Number:

713601099

FIELD INSPECTION FORM

Loc ID: 307697 Inspector Name: COSTA, RYAN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10351
Name of Operator: WAPITI OPERATING LLC
Address: 1251 LUMPKIN RD
City: HOUSTON State: TX Zip: 77043

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89235	WELL	PR	09/15/1999	CBM	071-06815	VPR C 4	RI

General Comment:

This is an inspection at the VPR C #4 wellsite.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Flow Line	# 1			
Comment:	There was gas venting out of the flowline along the access road. Operator was immediately notified. There was no signage and the gas was vented directly at the road way which is a safety concern. Inspector did not drive past the gas line and no other recent vehicle tracks were seen along the road which indicates venting had been going on for more than 8 consecutive hours.			
Corrective Action:	Comply with Rule 903.d.(2) Immediately cease venting. Submit form 4 to report gas venting.			Date: 06/13/2024

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 89235 Type: WELL API Number: 071-06815 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403820709	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582185
713601100	Inspection Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582180
713601101	Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582181