

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2024

Submitted Date:

06/11/2024

Document Number:

714201128**FIELD INSPECTION FORM**Loc ID 418028 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442175	TANK BATTERY	AC	06/24/2015		-	CREAM TANK BATTERY 15N-B28HZ	AC

**General Comment:**[THIS IS A TANK BATTERY INSPECTION.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	debris on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/25/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	iron		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	iron		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 19		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	#		
Comment:	21 total		
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	442175	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment						User		Date	
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Tuesday, June 11, 2024 at approximately 1400, I, Inspector Brittani Santistevan, conducted an on-site inspection at CREAM TANK BATTERY 15N-B28HZ (Kerr McGee Oil &amp; Gas Onshore), at location ID: 418028 in WELD COUNTY, Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be debris on multiple areas of location. Comply with Rule 606. (Corrective Action Date: June 25, 2024) See attached photo #3-5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>						santistb		06/11/2024	
Attached Documents									
You can go to ECMC Images ( <a href="https://ecmc.state.co.us/weblink/">https://ecmc.state.co.us/weblink/</a> ) and search by document number:									
Document Num	Description				URL				
403821450	INSPECTION SUBMITTED				<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582976">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582976</a>				
714201129	Photos				<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582964">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582964</a>				