

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/11/2024
Submitted Date:
06/12/2024
Document Number:
708904036

FIELD INSPECTION FORM

Loc ID 311532 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
16 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
ECMC Operator Number: 10550
Name of Operator: MUSTANG RESOURCES LLC
Address: PO BOX 13550
City: BAKERSFIELD State: CA Zip: 93389

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------|
| Toews, Wesley | | wtoews@blm.gov | |
| , Mustang | | nwelch@vaqueroenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------------|-------------|
| 210187 | WELL | PR | 10/01/2023 | GW | 045-05084 | JUHAN ASTRAL FED FEE 1-26-6S-94W | PR |

General Comment:

[CECMC Inspection Report Summary](#)
On 06/11/2024 at approximately 12:15 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad. Location # 311532 in Garfield County Colorado. Please refer to inspection 708903824 conducted on 05/16/2024, 3 of the 4 previous corrective actions have been completed. Corrective action for open ended load line has not been completed & CA date remains 05/27/2024 Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Equipment - Open ended load line with a CA date of 05/27/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection report.

Shared facilities with the SAVAGE 9-26-6-94 W pad, location # 311595

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Wellhead sign has mud on it & some required info is obscured | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 911/1-888-291-8588 | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Wire fencing | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Pipe rail fence | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Horizontal Heated Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------------|--|--|------------------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 5 | | |
| Comment: | Marked | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Open ended load line | | |
| Corrective Action: | All load lines will be capped or plugged | | Date: 05/27/2024 |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | Well on plunger lift | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | OTHER | STEEL AST | | |
| Comment: | Tank not equipped with telemetry | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 210 bbls | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 210187 Type: WELL API Number: 045-05084 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------------|
| Gravel | | | | | | Sparse to none |
| | | Culverts | | | | |
| | | Gravel | | | | |
| Compaction | | | | | | Small amount of light compaction |
| | | Ditches | | | | |
| | | Compaction | | | | Sparse to none in most sections |
| | | Rip Rap | | | | |

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Please refer to Equipment for observed compliance issue. | smelserw | 06/12/2024 |
| Shared facilities with the SAVAGE 9-26-6-94 W pad, location # 311595 | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 403822087 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6583797 |
| 708904037 | Inspection 708904036 Stormwater photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6583795 |
| 708904038 | Inspection 708904036 photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6583796 |