

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2024

Submitted Date:

06/13/2024

Document Number:

713400124

**FIELD INSPECTION FORM**

Loc ID 335844 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288287	WELL	PR	04/11/2012	GW	045-13180	CASCADE CREEK 697-16-32	PR
290124	WELL	PR	04/01/2020	GW	045-13997	CASCADE CREEK 697-15-01A	PR
290129	WELL	PR	07/11/2012	GW	045-13992	CASCADE CREEK 697-16-31	PR
290130	WELL	PR	09/17/2009	GW	045-13991	CASCADE CREEK 697-16-07	PR
290131	WELL	PR	09/01/2020	GW	045-13990	CASCADE CREEK 697-16-15A	PR
290133	WELL	PR	09/17/2009	GW	045-13988	CASCADE CREEK 697-15-17B	PR
290134	WELL	PR	04/21/2015	GW	045-13987	CASCADE CREEK 697-15-25	PR
290135	WELL	PR	03/01/2023	GW	045-13986	CASCADE CREEK 697-16-06	PR
290136	WELL	PR	10/18/2018	GW	045-13985	CASCADE CREEK 697-15-09A	PR
290138	WELL	PR	01/01/2008	GW	045-13983	CASCADE CREEK 697-09-64	PR

**General Comment:**

CECMC Inspection Report Summary

On 6/10/2024 at approximately 12:03, Compliance Inspector Dusty Popejoy conducted an on-site inspection at Laramie Energy LLC Cascade Creek 697-16-16 Pad at Location ID #335844 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

- 1) Equipment: Cellar, open entry to wildlife, refer to photos with a CA date of 6/20/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	1-800-891-6191 or 911		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	To pig launcher		
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Cellar, open entry to wildlife, refer to photos		
Corrective Action:	Cover all cellars with materials sufficient to prevent wildlife access.		Date: 06/20/2024
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	Telemetry on tanks				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	HEATED STEEL AST		,
Comment:	Telemetry on tanks				
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities										
Facility ID:	288287	Type:	WELL	API Number:	045-13180	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290124	Type:	WELL	API Number:	045-13997	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290129	Type:	WELL	API Number:	045-13992	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290130	Type:	WELL	API Number:	045-13991	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290131	Type:	WELL	API Number:	045-13990	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290133	Type:	WELL	API Number:	045-13988	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290134	Type:	WELL	API Number:	045-13987	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	290135	Type:	WELL	API Number:	045-13986	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Producing well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290136    Type: WELL    API Number: 045-13985    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290138    Type: WELL    API Number: 045-13983    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

<b>Completion</b>			
Operation:			
Date Flowback:			
Contractor:			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Ditches						
Compaction						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403823773	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585631">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585631</a>
713400125	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585630">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585630</a>