



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/14/2024
Submitted Date:
06/14/2024
Document Number:
696306410

FIELD INSPECTION FORM

Loc ID
159738

Inspector Name:
PETRIE, ERICA

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159794	WELL	PR	02/01/2024	OW	123-41043	State Antelope C12-W42-2HNC	PR
159795	WELL	PR	09/01/2023	OW	123-41044	State Antelope 11-41-2HNB	PR
159796	WELL	PR	09/01/2023	OW	123-41045	State Antelope 12-42-2HNB	PR
159797	WELL	PR	09/01/2023	OW	123-41046	State Antelope B12-V42-2HNC	PR
159798	WELL	PR	09/01/2023	OW	123-41047	State Antelope B-V-2HNB	PR
159799	WELL	PR	09/01/2023	OW	123-41048	State Antelope B11-V41-2HNC	PR
440683	WELL	PR	09/01/2023	OW	123-41071	State Antelope A-U-2HNB	PR
440684	WELL	PR	09/01/2023	OW	123-41072	State Antelope A11-U41-2HNC	PR
482397	WELL	PR	06/17/2023	OW	123-51721	State Antelope X-D-3HN	PR
482398	WELL	PR	06/17/2023	OW	123-51722	State Antelope C13-W43-2HN	PR
482399	WELL	PR	06/17/2023	OW	123-51723	State Antelope 13-43-2HN	PR
482400	WELL	PR	06/17/2023	OW	123-51724	Whitetail 14-44-35HN	PR
482401	WELL	PR	06/17/2023	OW	123-51725	State Antelope 41-11-3HN	PR
482402	WELL	PR	06/17/2023	OW	123-51726	State Antelope W-C-3HN	PR
482403	WELL	PR	06/17/2023	OW	123-51727	State Antelope V-B-3HN	PR
482404	WELL	PR	06/17/2023	OW	123-51728	State Antelope 42-12-3HN	PR
482405	WELL	PR	06/17/2023	OW	123-51729	State Antelope U-A-3HN	PR
482406	WELL	PR	06/17/2023	OW	123-51730	State Antelope 44-14-3HN	PR
482407	WELL	PR	06/17/2023	OW	123-51731	State Antelope 43-13-3HN	PR

Date Run: 6/21/2024 Doc [#696306410]

Page 1 of 6

General Comment:

[This is a Follow-Up Inspection to FIR 696305547 dated 12.19.2023](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Maintenance Tank - Now Reflects Current Operation			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	MT 45 Container t North Gas Lift Injection Meter House and MT 154 Container at South Gas Lift Injection Meter House are STILL missing Labels. Same Corrective Action Date Remains See photos			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 01/19/2024
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	159794	Type:	WELL	API Number:	123-41043	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	159795	Type:	WELL	API Number:	123-41044	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	159796	Type:	WELL	API Number:	123-41045	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	159797	Type:	WELL	API Number:	123-41046	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	159798	Type:	WELL	API Number:	123-41047	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	159799	Type:	WELL	API Number:	123-41048	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	440683	Type:	WELL	API Number:	123-41071	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	440684	Type:	WELL	API Number:	123-41072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482397	Type:	WELL	API Number: 123-51721 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482398	Type:	WELL	API Number: 123-51722 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482399	Type:	WELL	API Number: 123-51723 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482400	Type:	WELL	API Number: 123-51724 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482401	Type:	WELL	API Number: 123-51725 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482402	Type:	WELL	API Number: 123-51726 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	482403	Type:	WELL	API Number: 123-51727 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	PR			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	482404	Type:	WELL	API Number:	123-51728	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	482405	Type:	WELL	API Number:	123-51729	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	482406	Type:	WELL	API Number:	123-51730	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	482407	Type:	WELL	API Number:	123-51731	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Inspection.	petrie	06/14/2024
Chemical Container at North Gas Lift Injection Meter House MT 45 and MT 154 at South Gas Lift Injection Meter House are STILL missing Labels. See photos. Install sign to comply with Rule 605.h. Same Corrective Action Dated of 01.19.2024 applies		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403825958	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587767
696306411	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587764