

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2024

Submitted Date:

06/14/2024

Document Number:

713601125

FIELD INSPECTION FORM

Loc ID 321051 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HAHN, MIKE		mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205894	WELL	SI	08/01/2018	DSPW	009-06309	MCKINLEY 1-20-WD	RI
321051	LOCATION	AC			-	MCKINLEY-633S43W 20E2E2	RI

General Comment:

This is a location inspection of the MCKINLEY 1-20-WD wellsite.
See attached photos and additional details within this report.

Location

Lease Road:			
Type			
comment:	The access road has area where stormwater is pooling and vehicle rutting is occurring.		
Corrective Action:	Conduct road maintenance per Rule 1002.f.(2)C.	Date:	07/15/2024

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	There is out of service and unused equipment stored at the location that needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	07/15/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			
Lube Oil					
Comment:	There is oil leaking out of the compressor engine that has spilled onto the ground. Stained soils must be excavated and properly disposed. The oil in the engine skid will need to be cleaned up. Maintenance must be performed on equipment.				
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date:	06/21/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	3		STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Inspector Name: COSTA, RYAN

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	There is insufficient and no secondary containment of the tanks at the location for spill prevent. Berms will need to be rebuilt for secondary containment.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o. and 902.b.			Date:	07/15/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403825795	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587593
713601126	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587590