

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2024

Submitted Date:

06/14/2024

Document Number:

694100386

**FIELD INSPECTION FORM**

Loc ID 310932 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 2501 HARWOOD ST STE 1238  
City: DALLAS State: TX Zip: 75201

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Christopher	214-549-7215	kchambers@omimexpetroleum.com	
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	

**General Comment:**

This is an environmental inspection for Location ID 310932 Bledsoe Federal 14-20. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Statewide unnecessary equipment, weeds, waste, and trash requirements.  
Unused pipes and other equipment.  
Door to separator housing was blown down and laying on the ground.

Corrective Action: Comply with Rule 606

Date: 06/28/2024

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment: No liquid spills present during inspection.

Multiple Spills and Releases?

**Equipment:**

corrective date

Type:

#

Comment: Evidence of gas leak from a valve/vertical pipe was noted during an AVO inspection (primarily audible) while on location.

Corrective Action: Comply with Rule 608.e.

Date: 06/21/2024

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Evidence of a gas leak was observed while on site. High pitched sound caught the inspector's attention and it was narrowed down to a single vertical pipe releasing gas. No visible fume/plume or odors were detected, however there was a slight breeze at the time which may have hindered the visual and olfactory indicators.	robinsotl	06/14/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403825833	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587646">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587646</a>
694100387	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587645">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587645</a>