

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2024

Submitted Date:

06/17/2024

Document Number:

696306427

**FIELD INSPECTION FORM**

Loc ID: 432677 Inspector Name: PETRIE, ERICA On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432676	WELL	PR	04/01/2023	OW	123-37227	State Antelope U-Y-32HNB	PR
432754	WELL	SI	03/01/2024	OW	123-37267	State Antelope P-T-32HNB	SI
436243	WELL	PR	05/01/2023	OW	123-39003	STATE ANTELOPE P41-T44-32HNC	PR
436244	WELL	PR	04/01/2023	OW	123-39004	State Antelope 41-44-32HNB	PR
436826	WELL	SI	06/01/2023	OW	123-39279	STATE ANTELOPE U41-Y44-32HNC	SI

**General Comment:**

This is a Well PAD Inspection

**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:	Middle and East Methanol Tanks are missing Labels. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/19/2024
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Gas Meter Run	# 5		
Comment:	Gas Lift Injection Meters		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 432676 Type: WELL API Number: 123-37227 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432754 Type: WELL API Number: 123-37267 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436243 Type: WELL API Number: 123-39003 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436244 Type: WELL API Number: 123-39004 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436826 Type: WELL API Number: 123-39279 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI - Form 6A 403636904 with a Plug Due Date of 12.31.2028

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Methanol Tank missing labels</a>	petrie	06/17/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403827449	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590006">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590006</a>
696306428	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590002">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590002</a>