

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2024

Submitted Date:

06/24/2024

Document Number:

697602384**FIELD INSPECTION FORM**Loc ID 328397 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| ,            |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|-----------------------|-------------|
| 427610      | WELL                | PA     | 09/19/2023  | OW         | 123-35042 | REI H 09-31D          | EI          |
| 427612      | WELL                | PA     | 12/04/2023  | OW         | 123-35044 | REI H 09-30D          | EI          |
| 485974      | SPILL OR<br>RELEASE | CL     | 01/30/2024  |            | -         | REI H 09-30D Wellhead | EI          |

**General Comment:**

COGCC environmental inspection to determine progress on Spill ID 485974 / REI H 09-30D. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

| Location   |  |        |       |                            |
|--|--|--------|-------|----------------------------|
| <b>Lease Road:</b>                                     |  |        |       |                            |
| Type   | Access                                     |        |       |                            |
| comment:   | Lease Road has been seeded for reclamation |        |       |                            |
| Corrective ActionL                                     |  |        | Date: |                            |
| Overall Good: <input type="checkbox"/>                 |  |        |       |                            |
| Emergency Contact Number:                              |  |        |       |                            |
| Comment:   | <input type="text"/>                       |        |       |                            |
| Corrective Action:                                     | <input type="text"/>                       |        |       | Date: <input type="text"/> |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |       |                            |
| <b>Spills:</b>   |  |        |       |                            |
| Type   | Area                                       | Volume |       |                            |
| In Containment: No                                     |  |        |       |                            |
| Comment:   | <input type="text"/>                       |        |       |                            |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |       |                            |
| <b>Venting:</b>  |  |        |       |                            |
| Yes/No   |  |        |       |                            |
| Comment:   |  |        |       |                            |
| Corrective Action:                                     |  |        | Date: |                            |
| <b>Flaring:</b>  |  |        |       |                            |
| Type   |  |        |       |                            |
| Comment:   |  |        |       |                            |
| Corrective Action:                                     |  |        | Date: |                            |

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 427610 | Type: | WELL     | API Number: | 123-35042 | Status: | PA | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 427612 | Type: | WELL     | API Number: | 123-35044 | Status: | PA | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 485974 | Type: | SPILL OR | API Number: | -         | Status: | CL | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

