

Inspection Photos
Location: UPRR 42 Pan Am F #4
Spill ID: 480343



Photo 1 – Weeds



Photo 2 – Improper fencing



Inspection Photos
Location
Facility ID:




Photo 3 –



Photo 4 –



Inspection Photos
Location
Facility ID:




Photo 5 – Fencing torn



Photo 6 – Trash



Inspection Photos
Location
Facility ID:



Photo 7 –



Photo 8 –



Inspection Photos
Location
Facility ID:




Photo 9 – Stockpile and weeds



Photo 10 – Fencing does not properly surround excavation



Inspection Photos
Location
Facility ID:




Photo 11 – Fencing does not properly surround excavation



Photo 12 – Fencing does not properly surround excavation



Inspection Photos
Location
Facility ID:




Photo 13 – Fencing down



Photo 14 –



Inspection Photos
Location
Facility ID:




Photo 15 –



Photo 16 –



Inspection Photos

Location

Facility ID:



Photo 17 –



Photo 18 –



Inspection Photos

Location

Facility ID:



Photo 19 –



Photo 20 –

