

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2024

Submitted Date:

06/24/2024

Document Number:

697602388

**FIELD INSPECTION FORM**Loc ID 479010 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Peterson, John		jpetersen@kpk.com	KPK environmental
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Brown, Kari		kari.oakman@state.co.us	
,		cogcc@kpk.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480343	SPILL OR RELEASE	CL	01/13/2023		-	UPRR 42 Pan Am F #4	EI

**General Comment:**

COGCC environmental inspection to determine progress on Spill ID 480343. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds are overgrown within and outside of the excavation and through the excavation fencing.		
Corrective Action:	Comply with Rule 606.  Ongoing Issue: CA was originally issued on Inspection Document #689501444 on 11/7/2023.		Date: 11/14/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing around the excavations are inadequate. Fencing does not cover the entirety of the open excavation, and has fallen down around large portions of the excavation; weeds have grown through the fencing, tearing the fencing in multiple places. Current fencing is not adequate to keep out wildlife.		
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.  Ongoing Issue: CA was originally issued on Inspection Document #689501444 on 11/7/2023.		Date: 11/14/2023

**Equipment:**

Type: Flow Line	#		corrective date
Comment:	Flowline has been strung above ground and around open excavation. Flowline is active.		
Corrective Action:			Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	480343	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation excavation remains open. No water was observed within the excavation. No work has been done since the last inspection.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Quarterly reporting is required for Remediation Project #25934. Operator is past due on quarterly reporting. The last Supplemental Form 27 was received on December 20, 2022 (Doc #403253747).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule. Operator will maintain quarterly reporting until the site investigation is complete and the implementation schedule can be updated. This location was included in NOAV # 403513701 for violation of Rule 913.e.(3).

Date: 03/23/2023

CA originally issued on Inspection Document #689501444 on 11/7/2023.

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602389	Photolog	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599291">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599291</a>