

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/24/2024

Document Number:

698602129**FIELD INSPECTION FORM**Loc ID 316888 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 710Name of Operator: AEON ENERGY CORPAddress: 2600 SOUTH LEWIS WAY #102City: LAKEWOOD State: CO Zip: 80227**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                            | Comment |
|---------------|--------------|----------------------------------|---------|
| , Engineering |              | dnr_ecmc_engineering@state.co.us |         |
| Snyder, Barry | 303-922-0590 | aeonco@aol.com                   |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 272543      | WELL | PR     | 02/01/2023  | GW         | 115-06058 | HV RANCH CO 34-1 | SI          |

**General Comment:**Routine inspection.

**Location**

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Lease Road:</b> |   |       |  |
| Type               | Access  |       |  |
| comment:           | Two track off maintained County Road. Active agricultural cropland with seasonal access to well location. |       |  |
| Corrective Action  |   | Date: |  |

Overall Good: ☐

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | WELLHEAD                                 |       |            |
| Comment:             | Sign not posted at oil and gas location. |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.a.  | Date: | 07/26/2024 |
| Type                 | BATTERY                                  |       |            |
| Comment:             | Lease sign installed on meter shed.      |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | TANK LABELS/PLACARDS                     |       |            |
| Comment:             | Sign or label not posted on tanks.       |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.  | Date: | 07/08/2024 |

Emergency Contact Number:

Comment: Emergency contact information posted at Remote metering location.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | WEEDS  |       |  |
| Comment:           | Vegetation growing around equipment inside fencing at well location. |       |  |
| Corrective Action: |  | Date: |  |
| Type               | DEBRIS   |       |  |
| Comment:           | Production related debris inside wellhead fencing.                   |       |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☐

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | WELLHEAD  |       |  |
| Comment:           | Stock panel fencing around surface equipment at well location. Fencing is partially down and damaged. |       |  |
| Corrective Action: |   | Date: |  |

|                           |   |  |                 |
|---------------------------|---|--|-----------------|
| <b>Equipment:</b>         |   |  | corrective date |
| Type: Ancillary equipment | # 1   |  |                 |
| Comment:                  | Wellhead. Tubing in the wellbore. Tubing valve closed. Casing valve closed. |  |                 |

|                            |   |       |            |
|----------------------------|---|-------|------------|
| Corrective Action:         |   | Date: |            |
| Type: Other                | # 1   |       |            |
| Comment:                   | Meter Shed at remote Gas Meter Run.   |       |            |
| Corrective Action:         |   | Date: |            |
| Type: Horizontal Separator | # 1   |       |            |
| Comment:                   | Separator is off footings and laying at angle valves in and out of separator are closed. The 90 on flowline from well appears to have slipped threads. Flowline from separator to meter appears bent. |       |            |
| Corrective Action:         |   | Date: |            |
| Type: Gas Meter Run        | # 1   |       |            |
| Comment:                   | Remote Gas Meter Run located on access to HV Ranch 32-1. Gas Meter Run. Chart in Meter Box dated 6-1-24. Meter Calibration/Test Log dated 6-29-23. Well Inlet Valve open. Gas Outlet Valve open.      |       |            |
| Corrective Action:         |   | Date: |            |
| Type: Bradenhead           | # 0   |       |            |
| Comment:                   | Bradenhead inaccessible or not visible at surface.  |       |            |
| Corrective Action:         | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)   | Date: | 07/08/2024 |

**Tanks and Berms:**

| Contents           | #   | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1   | OTHER    | FIBERGLASS AST |         | ,      |
| Comment:           | Tank located at the remote metering location for the HV Ranch CO 34-1 and the Pratt 1R wells. Tank appears associated with the wells but there is no sign or label on tank. No emergency contact information or Content/Quantity/Hazard sign at tank. |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities  |        |       |      |             |           |         |    |               |    |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:  | 272543 | Type: | WELL | API Number: | 115-06058 | Status: | PR | Insp. Status: | SI |
| Idle Well   |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____   |        |       |      |             |           |         |    |               |    |
| <div>Comment: <div>Tubing in wellbore. Tubing valve closed. Casing valve closed. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.<br/><br/>Electronic Well File reflects last Production/Status reported 4/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is SI.</div></div> |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____ Date: _____  |        |       |      |             |           |         |    |               |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

|  |         |            |
|--|---------|------------|
| Comment  | User    | Date       |
| Well appeared to be Shut-In at time of inspection. Damaged fencing and Separator off footings looks like well equipment may have been possibly struck with farming equipment. No well sign noted at well location for emergency contact information. | stjohnw | 06/24/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                    |   |
|--------------|--------------------|---|
| Document Num | Description        | URL   |
| 698602138    | Inspection photos. | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599530">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599530</a> |