

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2024

Submitted Date:

06/18/2024

Document Number:

714201156**FIELD INSPECTION FORM**Loc ID 438174 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438173	WELL	PR	12/12/2014	OW	123-39892	Coalview G02-64-1HN	PR
438175	WELL	PR	12/12/2014	OW	123-39893	Coalview G02-63-1HN	PR

General Comment:[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	disconnected/unused gas meter. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	08/18/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Soundwall SE of location is in disrepair. See attached photos.		
Corrective Action:	Comply with 1002.f.(D).	Date:	08/18/2024
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Vertical Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:	total: 30		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 16		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity) 538 BBLs						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	500 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Comment: Shares containment with other tanks.						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	438173	Type:	WELL	API Number:	123-39892	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; it appears the valves are in the open position.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		01/16/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438175	Type:	WELL	API Number:	123-39893	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR; it appears the valves are in the open position.							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		01/16/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
				Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: partly sunny, dry ground.</p> <p>On Tuesday, June 18, 2024 at approximately 1300, I, Inspector Brittani Santistevan, conducted an on-site inspection at COALVIEW G 02-64-1HN PAD (Noble Energy), at location ID: 438174 in WELD COUNTY, Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. It appears to be a gas meter disconnected/unused. Reconnect or remove from location per Rule 606. (Corrective Action Date: August 18, 2024) See attached photo #4. 2. It appears the sound wall on the SE corner of location is in disrepair. Conduct maintenance on equipment and review self inspection processes per Rule 1002.f.(D). See attached photo #8. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	06/18/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403829146	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591770
714201160	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591767