

Inspection Photos

Loc: 483008

Operator: BNL (ENTERPRISE) INC

Inspection Date: 6/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the access road and location.



Inspection Photos



Photo 2. Facing toward the northwest side of the location. The silt fence is not maintained at the location. The loose soils along the access road at red arrow are not stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483008 | Date: 6/24/2024

Inspection Photos



Photo 3. Facing northeast at the location. The well has been drilled and liner was used during the drilling process..



Inspection Photos



Photo 4. Facing south toward the cuttings trench..



Inspection Photos



Photo 5. The tarp has become placed at the northeast side.



Inspection Photos



Photo 6. Facing toward the northeast side. This brush pile debris needs to be removed.



Inspection Photos



Photo 7. South side of the location facing east toward the topsoil pile. The topsoil has not been seeded and is not stabilized.



Inspection Photos



Photo 8. South side of the location facing west toward the topsoil pile. The topsoil has not been seeded and is not stabilized.

