

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2024

Submitted Date:

06/25/2024

Document Number:

696306461**FIELD INSPECTION FORM**Loc ID 435681 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435682	WELL	PR	04/23/2014	OW	123-38733	Antelope K21-O24-15HNB	PR
435683	WELL	PR	08/01/2023	OW	123-38734	Antelope 31-34-15HNB	PR
435684	WELL	PR	02/01/2024	OW	123-38735	Antelope K-O-15HNB	PR
435685	WELL	PR	04/23/2014	OW	123-38736	Antelope K31-O34-15HNB	PR

General Comment:

This is a Follow-Up Inspection to FIR 696305512 dated 12.14.2023

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	MT-56 Container STILL Missing Label; see photos Same Corrective Action Date remains		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	01/15/2024

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	435682	Type:	WELL	API Number: 123-38733 Status: PR Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	435683	Type:	WELL	API Number: 123-38734 Status: PR Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	435684	Type:	WELL	API Number: 123-38735 Status: PR Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	435685	Type:	WELL	API Number: 123-38736 Status: PR Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
ECMC Comments				
Comment	User	Date		
Routine Field Inspection. MT-56 STILL missing adequate Labeling	petrie	06/25/2024		
Attached Documents				
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:				
Document Num	Description	URL		
696306462	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6600481		