

# Inspection Photos

Loc: 484358

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 6/24/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward along the access road near the location. Topsoil was not salvaged along the road and soils are very compacted.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:484358 | Date: 6/24/2024



## Inspection Photos



**Photo 2.** Facing back west toward the flowline disturbance. The vegetation is not establishing along the flowline and there are vehicle tracks which a causing unnecessary disturbance. The flowline must be reclaimed and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484358 | Date: 6/24/2024



## Inspection Photos



**Photo 3.** There are vehicle tracks going outside of the flowline disturbance. All vehicles must remain on the original access road boundary.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:484358 | Date: 6/24/2024



## Inspection Photos



**Photo 4.** Facing east toward the wellsite.





## Inspection Photos



**Photo 5.** There absorbent cloths used for cleanup. Equipment should be repaired to prevent leaks.





## Inspection Photos



**Photo 6.** Facing toward the backside of the engine compressor.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:484358 | Date: 6/24/2024

## Inspection Photos



**Photo 7.** facing toward the south side of the compressor. Chemical barrels have been removed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:484358 | Date: 6/24/2024



## Inspection Photos



**Photo 8.** North side of the location facing south. The vegetation is not yet establishing at the disturbed interim areas.





## Inspection Photos



**Photo 9.** Facing east along the flowline. The vegetation is not establishing and soils are whitish and don't match the surrounding soils. Topsoil was not salvaged along the flowline which could be affecting vegetation. There are also vehicle tracks along the flowline causing unnecessary disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484358 | Date: 6/24/2024



## Inspection Photos



**Photo 10.** Facing west along the flowline. The vegetation is not establishing and soils are whitish and don't match the surrounding soils. Topsoil was not salvaged along the flowline which could be impacting revegetation. There are also vehicle tracks along the flowline causing unnecessary disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484358 | Date: 6/24/2024