

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

12/28/2023

Document Number:

403601159

## Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller  
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460  
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

## OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 321531 Location Type: Production Facilities  
Name: Helen Number: E1 Facilities  
County: BROOMFIELD  
Qtr Qtr: SESE Section: 23 Township: 1N Range: 68W Meridian: 6  
Latitude: 40.032634 Longitude: -104.963821

## Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

## Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473667 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 380086 Location Type: Well Site ☐  
Name: HELEN Number: 34-23  
County: BROOMFIELD No Location ID  
Qtr Qtr: SWSE Section: 23 Township: 1N Range: 68W Meridian: 6  
Latitude: 40.030840 Longitude: -104.967910  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material:  Date Construction Completed: 10/14/2010  
Maximum Anticipated Operating Pressure (PSI):  Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date:

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:****FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473666 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 321544 Location Type: Well Site ☐  
Name: HELEN Number: 4-6-23  
County: BROOMFIELD No Location ID  
Qtr Qtr: NWSE Section: 23 Township: 1N Range: 68W Meridian: 6  
Latitude: 40.035180 Longitude: -104.969020  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 10/22/2010  
Maximum Anticipated Operating Pressure (PSI): 160 Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/17/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the HELEN 4-6-23 (05-014-20708) was removed in its entirety via the open trench method. The trench was backfilled and the land surface graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473665 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 380084 Location Type: Well Site ☐

Name: HELEN Number: 43-23

County: BROOMFIELD No Location ID

Qtr Qtr: NESE Section: 23 Township: 1N Range: 68W Meridian: 6

Latitude: 40.034890 Longitude: -104.963140

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Date Construction Completed: 09/30/2010

Maximum Anticipated Operating Pressure (PSI): Testing PSI:

Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date:

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:****FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473664 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 380086 Location Type: Well Site ☐

Name: HELEN Number: 34-23

County: BROOMFIELD No Location ID

SWSE 23 1N 68W 6

Qtr Qtr: Section: Township: Range: Meridian:

Latitude: 40.030840 Longitude: -104.967910

Equipment at Start Point Riser: Well

#### **Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Date Construction Completed: 10/07/2010

Maximum Anticipated Operating Pressure (PSI): Testing PSI:

Test Date:

#### **OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date:

#### **Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

#### **FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473668 Flowline Type: Wellhead Line Action Type: Abandonment Verification

#### **OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

#### **Flowline Start Point Location Identification**

Location ID: 321544 Location Type: Well Site

Name: HELEN Number: 4-6-23

County: BROOMFIELD No Location ID

Qtr Qtr: NWSE Section: 23 Township: 1N Range: 68W Meridian: 6

Latitude: 40.035180 Longitude: -104.969020

Equipment at Start Point Riser: Well

#### **Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 09/23/2008

Maximum Anticipated Operating Pressure (PSI): 450 Testing PSI:

Test Date:

#### **OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/17/2023

#### **Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

#### **Description of Abandonment Verification:**

The flowline serving the Helen 33-23 (05-014-20649) was removed in its entirety via the open trench method. The trench was backfilled and the land surface graded.

## OPERATOR COMMENTS AND SUBMITTAL

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were removed:  
01420708\_FL: serviced Helen 4-6-23 (05-014-20708)  
01420649\_FL: serviced Helen 33-23 (05-014-20649)

Updated GIS data attached.  
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 12/28/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_ Director of ECMC Date: 6/26/2024

## CONDITIONS OF APPROVAL, IF ANY LIST

**COA Type**

**Description**

--	--

### ATTACHMENT LIST

**Att Doc Num**

**Name**

403601159	Form44 Submitted
403601268	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

### General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)