

Inspection Photos

Loc: 484360

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 6/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the flowline. The vegetation is not yet establishing.



Inspection Photos



Photo 2. Facing west by the location. There is still tree debris that has not been removed. Previous corrective action was not completed.



Inspection Photos



Photo 3. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484360 | Date: 4/22/2024

Inspection Photos



Photo 4. North side of the location facing south. Disturbed soils were reseeded but vegetation is not establishing very well yet.



Inspection Photos



Photo 5. North side of the location facing southwest.



Inspection Photos



Photo 6. Facing east at the location. The straw wattles have been placed at the disturbance area and where the slope is at the northwest side of location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484360 | Date: 4/22/2024

Inspection Photos



Photo 7. The stained soils have been cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484360 | Date: 4/22/2024

Inspection Photos



Photo 8. Facing east at the location. Disturbed soils have been seeded and will need to be monitored for vegetation establishment..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484360 | Date: 4/22/2024