

# Inspection Photos

API: 011-06032

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/26/2024

County: Bent



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location. There are tall undesirable weeds at the location that need to be controlled and removed. Previous CA was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing toward the meter shed. There is no secondary containment of the fuel/chemical tank behind the shed.



## Inspection Photos



**Photo 3.** There are plastic drums with no labeling and one appears to be empty and not in use.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-06032 | Date: 6/26/2024



## Inspection Photos



**Photo 4.** Facing toward the tank battery. There is insufficient secondary containment to contain a spill. Previous corrective action was not completed.



## Inspection Photos




**Photo 5.** The sign at the tank does not reflect the current Operator sand is faded. Previous CA was not completed.





## Inspection Photos



**Photo 6.** Facing northwest at the location.





## Inspection Photos



**Photo 7.** There is a dripping leak at the separator and stained soils. Previous corrective action was not completed.





## Inspection Photos



**Photo 8.** Facing toward the well. There is an uncapped pipe riser shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 011-06032 | Date: 6/26/2024