

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601181**FIELD INSPECTION FORM**Loc ID 321229 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY L		stacy@strachanexploration.com	
Harms, Jason		Jason@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206379	WELL	PR	08/01/2018	GW	011-06126	HOFFMAN, EARL 1	RI

General Comment:

This is a follow up of the previous reclamation inspection #713600502, #713600769.
The previous inspection corrective actions were not completed.
Non-compliance with the Rules will be referred to enforcement.
See attached photos and additional details within this report.

Note: Documentation (FIRR) showing completion of corrective actions is requested within 2 weeks.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	The sign is faded and does not meet the requirements. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/27/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 06/27/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601182	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603812