

Inspection Photos  
Location Name: Antelope 42-19 PAD  
Location ID: 413543



Energy and Carbon Management Commission  
40.38661, -104.35901, 4606.6ft  
06/24/2024 13:50:36

Photo 1 – Wellheads



Energy and Carbon Management Commission  
40.38668, -104.35903, 4596.4ft  
06/24/2024 13:50:52

Photo 2 – Wellhead Sign faded no longer visible

Inspection Photos  
Location Name: Antelope 42-19 PAD  
Location ID: 413543



Energy and Carbon Management Commission  
40.38678, -104.35904, 4594.9ft  
06/24/2024 13:51:11



Energy and Carbon Management Commission  
40.38675, -104.35892, 4596.5ft  
06/24/2024 13:51:41

Photo 3 – P-19 Wellhead

Photo 4 – Wellheads

Inspection Photos  
Location Name: Antelope 42-19 PAD  
Location ID: 413543



Photo 5 – Wellheads



Photo 6 – Wellhead Sign has faded no longer visible

Inspection Photos  
Location Name: Antelope 42-19 PAD  
Location ID: 413543



Energy and Carbon Management Commission  
40.38661, -104.35907, 4607.4ft  
06/24/2024 13:52:30

**Photo 7 – Wellhead Sign has faded no longer visible**



Energy and Carbon Management Commission  
40.38677, -104.35897, 4607.9ft  
06/24/2024 13:56:50

**Photo 8 – Wellheads – 42-19 Sign is on wrong well  
not 19G Sign is missing**

Inspection Photos  
Location Name: Antelope 42-19 PAD  
Location ID: 413543



**Photo 9 – Sign is on Wrong Missing. This 19G NOT  
42-19**