

# Inspection Photos

ID: 444661

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/26/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing northeast toward the compressor facility.



## Inspection Photos



**Photo 2.** Facing northeast toward the tank. The leak that had occurred was not cleaned up. There is insufficient labeling and signage at the tank. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 6/26/2024

## Inspection Photos



**Photo 3.** Facing east toward the tank. The leak that had occurred was not cleaned up. There is insufficient labeling and signage at the tank. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 6/26/2024

Inspection Photos



**Photo 4.** This photo was taken during the previous inspection on 3/15/2024.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 6/26/2024

Inspection Photos



**Photo 5.** The migratory bird nest has been removed since the previous inspection.

