

Inspection Photos

API: 099-06872

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/26/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. There are deep ruts in the road and there are now vehicle tracks driving off the two track which is widening the road. The vehicle ruts need to be repaired and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06872 | Date: 6/26/2024

Inspection Photos



Photo 2. Facing southwest at the wellsite. There was no sign posted at the wellsite.



Inspection Photos



Photo 3. Facing southwest by the well. There is unused equipment and drilling pipe that needs to be removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06872 | Date: 6/26/2024

Inspection Photos



Photo 4. Facing toward the fiberglass tank. The fence around the tank is not maintained to prevent livestock entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06872 | Date: 6/26/2024

Inspection Photos



Photo 5. The fence around the pumpjack is insufficient to prevent livestock entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06872 | Date: 6/26/2024