

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601194

FIELD INSPECTION FORM

Loc ID 314203 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
Jordan LaPlante		jordan_laplante@fws.gov	
Sanchez, Chris		chris.sanchez@state.co.us	
STACY L BEAR		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444661	GAS COMPRESSOR STATION	SI	12/21/2016		-	NEU Compressor	RI

General Comment:

This is a follow up of the previous inspection #713600839 at the NEU Compressor.
The corrective actions of the previous inspection have not been completed.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Tank battery sign and labels are missing and faded.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	The migratory bird nest has been removed from the top of the tank. It is unknown if the Operator consulted with CPW and USFWS. A follow up will be determined.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
Condensate	Tank			
Comment:	Previous inspection observed a leak at the tank that spilled E&P waste within the tank secondary containment. The spill has not been cleaned up since the previous inspection. Due to the amount spilled and no clean up performed, the Operator will need to submit a form 19 spill report to ensure proper clean up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste and contact EPS staff per Rule 912.b. 72 hours for Initial Form 19 Report			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601195	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604877