

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2024

Submitted Date:

06/29/2024

Document Number:

693807452

FIELD INSPECTION FORMLoc ID 311852 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		COGCCInspectionReports@terraep.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290100	WELL	IJ	01/01/2018	DSPW	103-11000	B-19N SWD #1	AC

General Comment:

Routine UIC inspection.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign on housing		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-285-9377		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Injection wellhead inside housing		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	290100	Type:	WELL	API Number:	103-11000	Status:	IJ	Insp. Status:	AC	
Underground Injection Control										
UIC Violation:				Maximum Injection Pressure:						
UIC Routine										
Inj./Tube:	Pressure or inches of Hg	1190	Previous Test Pressure			MPP				
	(e.g. 30 psig or -30" Hg)					Inj Zone:	FT-WS			
TC:	Pressure or inches of Hg	-4	Previous Test Pressure			Last MIT:	07/10/2023			
Brhd:	Pressure or inches of Hg	-2	Previous Test Pressure			AnnMTReq:				
Comment:	Routine UIC inspection. Active injection at time of inspection.									
Corrective Action:							Date:			
Method of Injection: PUMP FEED										
Test Type:			Tbg psi:			Csg psi:			BH psi:	
Insp. Status:										
Comment:										
Corrective Action:							Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807453	Inspection photos 6/24/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606832