

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1595 From entrance to location




Photo # 1596 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1597 Location



Photo # 1598 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1599 Location



Photo # 1600 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1601 Location



Photo # 1602 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1727 From inspection 708902717 conducted on 01/04/2024 Unused equipment – ECD disconnected



Photo # 1603 Unused equipment – ECD disconnected & not in use

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1728 From inspection 708902717 conducted on 01/04/2024 Unused equipment – ECD disconnected



Photo # 1604 Unused equipment – ECD disconnected & not in use

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1605 Unused equipment – ECD disconnected & not in use



Photo # 1606 Tank capacity illegible

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 13C-20-692 Pad

Location # 335379



Photo # 1607 Tank capacity illegible