

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2024

Submitted Date:

06/25/2024

Document Number:

696306463

FIELD INSPECTION FORM

Loc ID: 429977 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429977	LOCATION	AC			-	Antelope F-15 PAD	AC
429978	WELL	PR	05/11/2013	OW	123-35985	ANTELOPE F-J-15HNB	PR
438126	WELL	PR	11/01/2014	OW	123-39886	Antelope A-E-15HNB	PR
438127	WELL	PR	06/01/2023	OW	123-39887	Antelope A11-E14-15HNB	PR
438128	WELL	PR	10/27/2014	OW	123-39888	Antelope 11-14-15HNB	PR
438129	WELL	PR	10/26/2014	OW	123-39889	Antelope A11-E14-15HNC	PR
438130	WELL	PR	10/27/2014	OW	123-39890	Antelope A-E-15HNC	PR

General Comment:

This is a Follow-Up Inspection to FIR 696305514 dated 12.14.2023

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Tank Labels STILL remain unaddressed - EAST TANK BATTERY LABELS #1336 - NFPA and Content. #220404 - Content, Capacity and NFPA. #220403 - NFPA. #220402 - Capacity and Content. #220401 -NFPA. East side of East Tanks - far North Tank - Capacity. Far South Tank - Content, Capacity and NFPA. See photos Same Corrective Action Date remains the same		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/15/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Antelope 31-34-15HNB Separator Site; see photos		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.	Date:	06/28/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	429977	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	PR - Active Producing Production Facility								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	429978	Type:	WELL	API Number:	123-35985	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438126	Type:	WELL	API Number:	123-39886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438127	Type:	WELL	API Number:	123-39887	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438128	Type:	WELL	API Number:	123-39888	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438129	Type:	WELL	API Number:	123-39889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	438130	Type:	WELL	API Number:	123-39890	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments

Comment	User	Date
Routine Field Follow-Up Inspection. Tank Labels on East Side Tanks STILL REMAIN Unmarked Risers at 31-34-15HNB Separator Site	petrie	06/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403835224	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6600486
696306464	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6600482