

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



1. Lease sign at well site.



2. View of wellhead inside well house.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



3. Tubing pressure at time of inspection.



4. Casing pressure at time of inspection.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



5. Well location overview looking towards Tank Battery.
Note vegetation.



6. View of Tank Battery.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



7. View inside Steel Injection Pump Shed. Pump has been removed.



8. View of Injection Control and Equipment Building. Note vegetation.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



9. View of 200 BBL Fiberglass AST. Note vegetation, fluids, and equipment.



10. View of 400 BBL Steel AST's. Note vegetation and visible rust on tanks.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



11. Steel AST has hole rusted through wall of tank.



12. View of 400 BBL Fiberglass AST's.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



13. Visible staining of soil and concrete inside berms at tank battery.



14. Additional view of soil staining inside berms. Staining is present throughout the inside of the bermed containment area.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



15. Leaking Open Top Tank Trailer. Wet discolored soil area is approximately 30' X 17'.



16. Leak is emanating from bottom of trailer.

Inspection Photos
Location Name: Bowman SWD 3B-28-5-44
API Number: 125-09914



17. Containment berm opened up in front of Injection Pump making the berm inoperable as a BMP.



18. View looking East towards Tank Battery. This is the view that is visible of Facility from State Highway.