

Construction and Stormwater Inspection

Date: 06/25/2024

Operator: PROVIDENCE OPERATING LLC DBA POCO
OPERATING - 10694

Location ID: 451646

Inspection Document #: 708201354

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



6/25/24, 10:19 AM
6° N
ECMC

Photo 1. Form 2A posted on location in compliance with Rule 406.c

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 2. Southeast corner of the drilling pad. Stormwater BMPs appear to have been repaired and slopes have been stabilized with crimped mulch observed.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 3. Southeast corner of the drilling pad, facing north. See comments in Photo 2.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 4. Southeast corner of the location. Perimeter stormwater ditch and berm, and topsoil stockpile pictured.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 5. Eastern portion of the topsoil stockpile. Topsoil appears to have been salvaged in compliance with Rule 1002.b and stabilized with the evidence of crimped mulch and drill rows, in compliance with Rule 1002.c.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 6. Eastern portion of the topsoil stockpile, facing south. See comments in Photo 5.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 7. Northern portion of the topsoil stockpile, facing south. See comments in Photo 5.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 8. Western portion of the topsoil stockpile, facing southeast. See comments in Photo 5.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 9. Top portion of the topsoil stockpile, facing north. See comments in Photo 5.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 10. Sediment trap and ditch and berm installed on the northeastern/northern portion of the construction area.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 11. Facing southeast; see comments in Photo 10.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 12. Sediment trap and ditch and berm installed on the northwestern portion of the construction area.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 13. Perimeter ditch and berm installed along the western portion of the construction area.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 14. Facing southeast; see comments in Photo 13.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 15. Netting does not appear to have been repaired since the previous inspection. Additionally, free fluids observed within secondary containment need to be properly disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 6. Stained soil observed west of tank battery.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 17. Debris within tank battery secondary containment.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 18. Previously documented stained soils appear to have been removed and disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 19. Previously documented unused equipment appears to have been removed.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 20. Oily rags (debris) observed within tank battery secondary containment.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 21. Free fluids observed within compressor skid on west side of location.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 22. Free fluids observed within compressor skid on west side of location.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 23. Stained soil around wellheads appears to have been removed and disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 24. Stained soil around wellheads appears to have been removed and disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 25. Stained soil around wellheads appears to have been removed and disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 26. Stained soil south of wellheads.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 27. No wildlife netting observed around secondary containment on west end of location.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 28. No wildlife netting observed around secondary containment on west end of location. Additionally, free fluids need to be properly removed and disposed of.

Inspection Photos
Location Name: Brighton Lakes 20-17
Location ID: 451646



Photo 29. Weedy vegetation on the west end of the location appears to have been mowed. The Operator will need to continue to monitor and manage the location for undesirable vegetation.