

Interim Reclamation and Stormwater Inspection

Date: 06/25/2024

Operator: PDC ENERGY INC - 69175

Location ID: 436062

Inspection Document #: 708201360

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 1. Undesirable vegetation (kochia, curly dock) and CO Noxious Weeds (List B - canada thistle, scotch thistle; List C - cheatgrass) observed at the location entrance. This portion of the location does not appear to have been managed for weeds.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 2. Continued from Photo 1. Also pictured, trash and debris.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 4. See comments in Photo 1.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 5. Southwest portion of the location; See comments in Photo 1.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 6. Stained soil at compressor skid.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062




Photo 7. Stained soil within secondary containment.



Photo 8. Wildlife netting requires repair/replacement.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062




Photo 9. Stained soil at wellhead.

Inspection Photos
Location Name: Sharp 24-3-11HC
Location ID: 436062



Photo 10. Northeast corner of the location. Weeds along the northern and eastern portions appear to have been sprayed with herbicide. The southern portion of the location near the entrance does not appear to have been sprayed; refer to Photos 1-5 for additional.