

Construction and Stormwater Inspection

Date: 06/26/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 483513

Inspection Document #: 708201369

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 1. Facing south on WCR 51, near the location entrance. Vehicle track out observed originating from the location entrance.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 2. Continued from Photo 1, facing south.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 3. Facing north on WCR 51, south of the location entrance. Vehicle track out observed originating from the location entrance.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 4. Form 2A posted on location.



Photo 5. Northeast corner of the construction area. Temporary BMPs (filtrexx wattles) have been installed along the entire perimeter during the construction phase. More permanent BMPs should be selected and installed upon completion of the pad.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 6. Topsoil stockpile on the eastern portion of the pad; topsoil salvage activities were ongoing at the time of this inspection.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 7. Facing northwest along the eastern portion of the location; see comments in Photo 6.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 8. Topsoil salvage activities were ongoing at the time of this inspection. The Operator shall ensure that all topsoil is salvaged from the location, in compliance with Rule 1002.b.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 9. Southeast corner of the construction area. Temporary BMPs (filtrexx wattles) have been installed along the entire perimeter during the construction phase. More permanent BMPs should be selected and installed upon completion of the pad.



Photo 10. Southwest corner of the construction area. Temporary BMPs (filtrexx wattles) have been installed along the entire perimeter during the construction phase. More permanent BMPs should be selected and installed upon completion of the pad.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 11. Topsoil stockpile on the western portion of the location. Topsoil salvage activities were ongoing at the time of this inspection.



Photo 12. West/center portion of the construction area. Temporary BMPs (filtrex wattles) have been installed along the entire perimeter during the construction phase. More permanent BMPs should be selected and installed upon completion of the pad.



Photo 13. Northwest corner of the construction area. Temporary BMPs (filtrexx wattles) have been installed along the entire perimeter during the construction phase. More permanent BMPs should be selected and installed upon completion of the pad.

Inspection Photos
Location Name: A07-08 Facility
Location ID: 483513



Photo 14. Overview of the location construction area; a follow-up inspection will be performed at a later date to ensure compliance with ECMC Rules.