

# Construction and Stormwater Inspection

Date: 06/26/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 483562

Inspection Document #: 708201370

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



Photo 1. Form 2A posted on location.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 2.** Taken near the start of the access road, facing north. At the time of this inspection, it did not appear that all topsoil had been salvaged from the access road but rather it appeared to have been grubbed of vegetation and graded. Operator shall ensure that all topsoil is salvaged in accordance with Rule 1002.b.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 3.** Taken from the access road, facing north. See comments in Photo 2.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 4.** Taken from the access road, facing north. See comments in Photo 2.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 5.** Taken from the access road, facing south. See comments in Photo 2.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 6.** Taken from the access road, facing northeast. See comments in Photo 2.



**Photo 7.** Taken from the northernmost point of the access road, facing south. Access road construction did not advance north of the canal crossing at the time of this inspection.

Inspection Photos  
Location Name: A12-02 Pad  
Location ID: 483562



**Photo 8.** See comments in Photo 7.