


Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



1. Lease sign at wellhead.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



3. Open valve with broken off pressure gauge stem still in valve.



4. Tubing pressure at time of inspection.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



5. Casing pressure at time of inspection.



6. Debris and unused equipment on location. Note vegetation.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



7. Unused tank on location. Note missing hatch cover.



8. View of Tank Battery. Note vegetation.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



9. View of steel 400 BBL tank. Note rust streak and holes in tank walls.



10. View of 200 BBL Fiberglass tank. Note missing labels, missing hatch cover, and vegetation.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



11. View of the backside of Injection Building and buried plastic tank.



12. Tank has no labels or sign and is completely full at time of inspection.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



13. Two track access turn off from maintained CR.



14. Well site overview.

Inspection Photos
Location Name: Bledsoe SWD 1-18-3-43
API Number: 125-09352



15. Overview of area around Injection Building. Note trash, vegetation, and unused equipment.



16 Location overview. Note vegetation.