

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2024

Submitted Date:

07/02/2024

Document Number:

698602149**FIELD INSPECTION FORM**Loc ID 336736 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**37 Number of Comments16 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone | Email                            | Comment                 |
|-------------------|-------|----------------------------------|-------------------------|
| Taylor, Chad      |       | chad.taylor@state.co.us          |                         |
| Lindley, Trent    |       | trent.lindley@state.co.us        | NAOV Specialist         |
| Kirschner, Steven |       | steven.kirschner@state.co.us     | Enforcement Supervisor  |
| Quint, Craig      |       | craig.quint@state.co.us          | E Compliance Supervisor |
| Chambers, Kit     |       | Kchambers@ravenwoodlabs.com      | 7/16/2023               |
| , Engineering     |       | dnr_ecmc_engineering@state.co.us |                         |
| Pesicka, Conor    |       | conor.pesicka@state.co.us        |                         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 278717      | WELL | IJ     | 04/01/2021  | DSPW       | 125-09352 | BLED SOE SWD 1-18-3-43 (OWP) | SI          |

**General Comment:**

Routine 2024 UIC inspection. Location inspection was also completed to document location conditions at time of inspection.

| Location                               |   |       |            |
|--|---|-------|------------|
| <b>Lease Road:</b>                     |   |       |            |
| Type                                   | Access  |       |            |
| comment:                               | Two track off maintained County Road. The access two track and location surface area have not been maintained. Site and roads are over grown with vegetation creating an extremely hazardous condition hiding obstructions and discarded equipment on location.   |       |            |
| Corrective Action                      | Repair and maintain lease road to comply with rule 603.I  | Date: | 08/02/2024 |
| Overall Good: <input type="checkbox"/> |   |       |            |
| <b>Signs/Marker:</b>                   |   |       |            |
| Type                                   | BATTERY   |       |            |
| Comment:                               | Sign not posted at battery.   |       |            |
| Corrective Action:                     | Install sign to comply with Rule 605.e.   | Date: | 08/02/2024 |
| Type                                   | TANK LABELS/PLACARDS  |       |            |
| Comment:                               | Tank Battery placards are peeling, sun bleached and unreadable.   |       |            |
| Corrective Action:                     | Install sign to comply with Rule 605.h.   | Date: | 08/02/2024 |
| Type                                   | OTHER   |       |            |
| Comment:                               | Buried plastic tank at injection room facility has no label or signage. Tank is full.<br><br>Previously documented in FIR dated 6/27/2023 Document Number 698600718 corrective action has not been completed by Operator. Corrective action date remains the same to document period of non-compliance.                                 |       |            |
| Corrective Action:                     | Install sign to comply with Rule 605.g.   | Date: | 08/16/2023 |
| Type                                   | WELLHEAD  |       |            |
| Comment:                               | Lease sign at wellhead.   |       |            |
| Corrective Action:                     |   | Date: |            |
| Emergency Contact Number:              |   |       |            |
| Comment:                               | Repeated attempts to call posted emergency contact #877-425-4882. Number does not go through resulting in disconnect.<br><br>Previously documented in FIR dated 6/27/2023 Document Number 698600718 corrective action has not been completed by Operator. Corrective action date remains the same to document period of non-compliance. |       |            |
| Corrective Action:                     | Install sign to comply with Rule 605.d.   | Date: | 08/16/2023 |
| <b>Good Housekeeping:</b>              |   |       |            |
| Type                                   | DEBRIS  |       |            |
| Comment:                               | Production related debris and trash on location, inside injection pump and equipment building.  |       |            |
| Corrective Action:                     | Comply with Rule 606.   | Date: | 07/10/2024 |
| Type                                   | UNUSED EQUIPMENT  |       |            |
| Comment:                               | Production related equipment, parts, and pipe scattered across location.  |       |            |
| Corrective Action:                     | Comply with Rule 606.   | Date: | 07/18/2024 |
| Type                                   | WEEDS   |       |            |
| Comment:                               | The Location has not been maintained. Site and roads are over grown with vegetation creating an extremely hazardous condition hiding obstructions and discarded equipment on location.  |       |            |
| Corrective Action:                     | Comply with Rule 606.   | Date: | 07/10/2024 |
| Overall Good: <input type="checkbox"/> |   |       |            |

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               | LOCATION                               |       |  |
| Comment:           | Post and wire fencing around location. |       |  |
| Corrective Action: |  | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Other               | # 1  |       |                 |
| Comment:                  | Filter Pot.  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Deadman # & Marked  | # 4  |       |                 |
| Comment:                  | Anchor Markers are down.   |       |                 |
| Corrective Action:        | Install proper guy line markers per Rule 603.j   | Date: | 07/17/2024      |
| Type: Bradenhead          | # 1  |       |                 |
| Comment:                  | Bradenhead plumbed to surface.   |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 1  |       |                 |
| Comment:                  | Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve closed, not connected. |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Other               | # 1  |       |                 |
| Comment:                  | Power panel.   |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Flow Line           | # 2  |       |                 |
| Comment:                  | Above grade Valve set with steel tube barrier.   |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Other               | # 1  |       |                 |
| Comment:                  | Electric Pump  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Other               | # 1  |       |                 |
| Comment:                  | Steel 10' X 20' Injection Pump and Control Building. Broken windows.                     |       |                 |
| Corrective Action:        |  | Date: |                 |

**Tanks and Berms:**

| Contents | # | Capacity | Type        | Tank ID | SE GPS |
|----------|---|----------|-------------|---------|--------|
| OTHER    | 1 |          | PBV PLASTIC |         | ,      |

|                    |  |                  |
|--------------------|--|------------------|
| Comment:           | Buried Plastic Tank on backside of Injection Building. No labels, no sign, and tank is full.<br><br>Per Rule 609.a Operators will promptly investigate, and if appropriate, repair, replace, or remediate any malfunctioning equipment or process. |                  |
| Corrective Action: | Comply with Rule 609.a   | Date: 07/18/2024 |

Paint

|                  |                   |
|------------------|-------------------|
| Condition        |                   |
| Other (Content)  | No label or sign. |
| Other (Capacity) |                   |
| Other (Type)     |                   |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           | None.    |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |  |          |                |         |        |
|--------------------|--|----------|----------------|---------|--------|
| Contents           | #                                      | Capacity | Type           | Tank ID | SE GPS |
| PRODUCED WATER     | 1                                      | 400 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           | Tank labels are fading and unreadable. |          |                |         |        |
| Corrective Action: |  |          |                |         | Date:  |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              |          |                     |                     |             |
| Comment:           | Shared.  |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |  |          |           |         |                  |
|--------------------|--|----------|-----------|---------|------------------|
| Contents           | #  | Capacity | Type      | Tank ID | SE GPS           |
| PRODUCED WATER     | 1  | 400 BBLS | STEEL AST |         | ,                |
| Comment:           | Tank has a hole through the wall of the tank. Tank is rusted, pitted, or peeling paint, or show evidence of inadequate repair. |          |           |         |                  |
| Corrective Action: | Inspect, maintain and repair tanks to comply with rule 609.b.  |          |           |         | Date: 08/02/2024 |

Paint

|                  |            |
|------------------|------------|
| Condition        | Inadequate |
| Other (Content)  |            |
| Other (Capacity) |            |
| Other (Type)     |            |

Berms

|       |          |                     |                     |             |
|-------|----------|---------------------|---------------------|-------------|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Insufficient  | Base Insufficient   | Inadequate  |

|                    |   |  |                |         |        |                  |  |
|--------------------|---|--|----------------|---------|--------|------------------|--|
| Comment:           |   | Berms walls and base have vegetation growing inside and on berms.  |                |         |        |                  |  |
| Corrective Action: |   | Repair or install berms or other secondary containment devices per Rule 603.o.   |                |         |        | Date: 08/02/2024 |  |
| Contents           | # | Capacity   | Type           | Tank ID | SE GPS |                  |  |
| OTHER              | 1 | 200 BBLs   | FIBERGLASS AST |         | ,      |                  |  |
| Comment:           |   | Tank 50' S/SE from Tank Battery not identified as out of service and OOSLAT (OUT OF SERVICE LOCKS AND TAGS) compliant.<br>Hatch cover missing. |                |         |        |                  |  |
| Corrective Action: |   | Comply with Rule 609.c.  |                |         |        | Date: 08/02/2024 |  |

**Paint**

|                  |                   |  |  |  |  |  |  |
|------------------|-------------------|--|--|--|--|--|--|
| Condition        |                   |  |  |  |  |  |  |
| Other (Content)  | No label or sign. |  |  |  |  |  |  |
| Other (Capacity) |                   |  |  |  |  |  |  |
| Other (Type)     |                   |  |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |  |       |  |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |       |  |
|                    |          |                     |                     |             |  |       |  |
| Comment:           |          | None.               |                     |             |  |       |  |
| Corrective Action: |          |                     |                     |             |  | Date: |  |

|                    |   |  |                |         |        |                  |  |
|--------------------|---|--|----------------|---------|--------|------------------|--|
| Contents           | # | Capacity   | Type           | Tank ID | SE GPS |                  |  |
| PRODUCED WATER     | 1 | 200 BBLs   | FIBERGLASS AST |         | ,      |                  |  |
| Comment:           |   | Gauge hatch missing.   |                |         |        |                  |  |
| Corrective Action: |   | Close and seal gauge hatches when not accessing tank per Rule 608.a.(9). |                |         |        | Date: 07/04/2024 |  |

**Paint**

|                  |          |  |  |  |  |  |  |
|------------------|----------|--|--|--|--|--|--|
| Condition        | Adequate |  |  |  |  |  |  |
| Other (Content)  |          |  |  |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |  |  |
| Other (Type)     |          |  |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |  |       |  |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |       |  |
| Earth              |          |                     |                     |             |  |       |  |
| Comment:           |          | Shared              |                     |             |  |       |  |
| Corrective Action: |          |                     |                     |             |  | Date: |  |

**Venting:**

|                    |  |  |  |  |                  |  |
|--------------------|--|--|--|--|------------------|--|
| Yes/No             | YES  |  |  |  |                  |  |
| Comment:           | Inspector found Tubing valves open on the wellhead at time of inspection. A one inch valve on the Tubing used for pressure checks was also open with the pressure gauge broken off. Stem of gauge was still in valve effectively allowing the well to vent or be open to atmosphere. |  |  |  |                  |  |
| Corrective Action: | Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).  |  |  |  | Date: 07/18/2024 |  |

**Flaring:**

|          |  |  |  |  |  |  |  |
|----------|--|--|--|--|--|--|--|
| Type     |  |  |  |  |  |  |  |
| Comment: |  |  |  |  |  |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Inspected Facilities**Facility ID: 278717 Type: WELL API Number: 125-09352 Status: IJ Insp. Status: SI**Underground Injection Control**UIC Violation: Other Maximum Injection Pressure: \_\_\_\_\_UIC Routine

Inj./Tube: Pressure or inches of Hg 0.0 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: LKMR

TC: Pressure or inches of Hg 0.0 Previous Test Pressure \_\_\_\_\_ Last MIT: 03/22/2021

Brhd: Pressure or inches of Hg 0.0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: 06/27/2024 inspection - Tubing= 0.0 PSIG. Casing= 0.0 PSIG . Bradenhead = 0.0. Suspect possible casing leak.

06/27/2023 inspection - Tubing = 0 psi, Casing = -10 psi, BH = 0 psi. Last MIT 3/22/2021. Possible casing leak.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports. Last submitted production report 8/1/2022.

FIR dated 6/27/2023 Document Number 698600718 corrective action's have not been completed by Operator. Corrective action date remains the same to document period of non-compliance.

Corrective Action: **Immediately shut in well and disconnect flowline or disable/LOTO injection pump. (Tubing valve shut at wellhead by inspector.)**Date: 07/14/2023**Perform MIT per Rule 417.a****Submit required Form 7(s) to COGCC per rule 413**Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment   | User    | Date       |
|---|---------|------------|
| 06/27/2023 FIR Document Number 698600718 corrective action's have not been addressed by Operator. Operator has no employees maintaining or checking well, location, or equipment on a routine basis. Location is not secure and vulnerable to unauthorized entry with possibility of personal injury, vandalism, and thief. | stjohnw | 07/02/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description        | URL   |
|--------------|--------------------|---|
| 698602152    | Inspection photos. | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6610254">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6610254</a> |