

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/26/2024

Document Number:

713301015**FIELD INSPECTION FORM**Loc ID 318447 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                    | Comment                         |
|---------------|--------------|--------------------------|---------------------------------|
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us |                                 |
| , KPK         | 303-825-4822 | cogcc@kpk.com            | <a href="#">all inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 241308      | WELL | PR     | 07/01/2023  | GW         | 123-09097 | ALEX H MILLER 2 | PR          |

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | good     |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

|                           |                             |                  |
|---------------------------|-----------------------------|------------------|
| <b>Good Housekeeping:</b> |                             |                  |
| Type                      | WEEDS                       |                  |
| Comment:                  | Overgrown vegetation, weeds |                  |
| Corrective Action:        | Comply with Rule 606        | Date: 07/03/2024 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                     |       |
|--------------------|-------------------------------------|-------|
| <b>Fencing/:</b>   |                                     |       |
| Type               | PUMP JACK                           |       |
| Comment:           | safety guards                       |       |
| Corrective Action: |                                     | Date: |
| Type               | OTHER                               |       |
| Comment:           | electrical disconnect, metal panels |       |
| Corrective Action: |                                     | Date: |

|                           |                              |       |                 |
|---------------------------|------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                              |       | corrective date |
| Type: Bradenhead          | # 1                          |       |                 |
| Comment:                  | pipd to surface              |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Ancillary equipment | # 3                          |       |                 |
| Comment:                  | electrical disconnect panels |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Prime Mover         | # 1                          |       |                 |
| Comment:                  | electric                     |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Pump Jack           | # 1                          |       |                 |
| Comment:                  |                              |       |                 |
| Corrective Action:        |                              | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

**Inspected Facilities**Facility ID: 241308 Type: WELL API Number: 123-09097 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 01/08/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <p>ECMC Inspection Report Summary<br/>Inspector Michael Kester,<br/>conducted an on-site inspection.<br/>Location: Alex H Miller #2<br/>Operator: KPK<br/>API#: 123-09097<br/>County: Weld<br/>While there, I observed well site,<br/>During this inspection the following possible compliance issues were observed:</p> <p>Overgrown vegetation, comply with Rule 606, corrective action date 7-3-2024, photos 1 &amp; 2</p> <p>Weather conditions: over cast and dry<br/>A follow up on this site inspection needs to be conducted to ensure the<br/>Compliance issues have been corrected to comply with ECMC rules.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC<br/>This is a continuing education inspection</p> | kesterm | 06/26/2024 |

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403837897    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603223">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603223</a> |
| 713301016    | site pic             | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603222">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603222</a> |