

Inspection Photos

June 28th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 454942

Inspection Document #: 714000914

Dolores County, CO

Township: SESW 8 40N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942

6/28/24
+37.756502,-108.770720
60° NE



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of interim reclamation conducted, vegetation is progressing in these areas.

API #: 033-06184, 06186

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942



Photo 3. View of north cut slope and spoil pile which are covered in annual weeds, including Cheatgrass.

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942



Photo 4. View of Musk thistle observed in both the northern and southern portions of the disturbance.

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of storm water BMPs that are functioning and have been properly maintained near the access point of the disturbance.

API #: 033-06184, 06186

Inspection Photos
Location Name: DC 22, 24
Location ID: 454942



6/28/24
+37.736645,-108.751043
186° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of reference area comprised predominantly of Sage brush and Serviceberry.

API #: 033-06184, 06186