

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2550 From entrance to location



Photo # 2551 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2552 Location



Photo # 2553 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2554 Location



Photo # 1802 from inspection 708900877 conducted on
06/26/2023 - Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 9872 From inspection 708903328 conducted on 03/13/2024 Unused equipment/ECD disconnected



Photo # 2555 Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1803 from inspection 708900877 conducted on 06/26/2023 - Unused equipment/ECD disconnected



Photo # 9873 From inspection 708903328 conducted on 03/13/2024 Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2556 Unused equipment/ECD disconnected



Photo # 2557 Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548




Photo # 9871 From inspection 708903328 conducted on 03/13/2024 Cellar cover not properly installed/wildlife & personnel hazard & wildlife egress not properly installed.




Photo # 2558 Cellar cover not properly installed/wildlife & personnel hazard & wildlife egress not properly installed.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2559 Cellar cover not properly installed/wildlife & personnel hazard & wildlife egress not properly installed.



Photo # 2560 Cellar cover not properly installed/wildlife & personnel hazard & wildlife egress not properly installed.