

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

701104043**FIELD INSPECTION FORM**Loc ID 312605 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Byers, Jim		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222004	WELL	PR	03/01/2021	GW	077-08606	WAGON TRAIL 44-11	EG
486430	GAS GATHERING PIPELINE SYSTEM	AC	11/13/2023		-	Wagon Trail Gas Gathering	EG

**General Comment:****Flowline Integrity Inspection**

2" poly pipe is exposed in several areas of the access road into the Wagon Trail 44-11 wellsite. Exposed pipe is on the road and a long the road both.

Inspect and maintain flowline integrity (1102.i. Maintenance.)

Take measures to protect flowline from damage and being a danger to recreation vehicle traffic.

Contacted Matt Kasten with Laramie by phone 6/27/24 12:30pm to communicate the concerns laid out in this inspection.

Inspected Facilities									
Facility ID:	222004	Type:	WELL	API Number:	077-08606	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	486430	Type:	GAS	API Number:	-	Status:	AC	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403838760	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604239">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604239</a>
701104044	Flowline integrity inspection 701104043 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604238">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604238</a>