

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2024

Submitted Date:

06/26/2024

Document Number:

707800990

FIELD INSPECTION FORM

Loc ID: 324580 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212003	WELL	PR	08/01/2022	OW	057-05049	MCCALLUM UNIT 19	PR

General Comment:

3ECMC Inspection Report Summary
On Monday 6/11/2024, I, Inspector Scott Ramsey, conducted a routine inspection at KPK McCallum 19, at Location # 324580 in Jackson county Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
During this inspection the following possible compliance issues were observed:
1. No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.
2. Belt guard missing from pump jack
3. Well head signage lacking information
4. Load line missing cap/bull plug
5. Lacking tank battery signage
6. Some weeds

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well head signage lacking information		
Corrective Action:	provide proper labeling	Date:	08/02/2024
Type	BATTERY		
Comment:	Lack of tank battery signage		
Corrective Action:	Provide proper signage	Date:	08/02/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Belt guard missing from pump jack		
Corrective Action:	Eliminate possibility of wildlife or personnel from being harmed from equipment.	Date:	08/02/2024
Type	OTHER		
Comment:	Load line missing cap/bull plug		
Corrective Action:	install cap/plug	Date:	08/02/2024
Type	WEEDS		
Comment:	Weeds around equipment		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Type: Other		# 1		
Comment:	Well head			
Corrective Action:			Date:	
Type: Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth						
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 212003 Type: WELL API Number: 057-05049 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403838864	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604320
707800995	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604313