

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2024

Submitted Date:

07/11/2024

Document Number:

713301033**FIELD INSPECTION FORM**Loc ID 335913 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CivitasResources		Inspections@civiresources.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295524	WELL	PR	01/05/2024	GW	013-06583	SHAFFER NEWMAN 24-13	PA

General Comment:[rig inspection](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	good			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	chain link panels			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	#			corrective date
Comment:	piped to surface			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 295524 Type: WELL API Number: 013-06583 Status: PR Insp. Status: PA**BradenHead**Date of Last Brhd Test: 01/25/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 267 Fluid Type: GASEnd Surf Csg Pressure: 60Comment: Corrective Action: Date: **Workover**Comment: AXIS rig 28 P&A well, pumping cement at time of inspectionCorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site rig inspection.</u> <u>Location: Shaffer Newman 24-13</u> <u>Operator: Crestone Peak</u> <u>API#: 013-06583</u> <u>County: Boulder</u> <u>While there, I observed rig onsite working to P&A well</u> <u>Weather conditions: over cast and dry</u> <u>This inspection does not nullify any orders or NOAV from the ECMC</u> <u>This is a continuing education inspection</u>	kesterm	07/11/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301034	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619848